

## Janome MB-4 Design Transfer

1. Turn on your Janome MB-4.
  2. Touch screen to initialize your embroidery arm
  3. Place you Jump drive(512 or less is recommended) into the USB port on MB-4
  4. Touch the file folder icon on the left side of the screen. Wait for the machine to detect the jump drive. This may take a few seconds(be patient)
  5. Once the jump drive is formatted, select the jump drive icon on the right side of the screen and you will see a folder named EMBF
  6. Then select the “X” on the screen and remove the jump drive .
- The First 6 steps are only necessary when using a new jump drive for the first time.**
7. Now go to your computer and place the jump drive into the USB port.
  8. Click on Start, then click on My Computer
  9. Go to where your designs are saved on your computer. Make sure that your design is not too big (8”x9”) for your embroidery area and the designs are in the JEF+, JEF, & DST format. Leave this window open on your computer desktop
  10. Go back to Start, then click on My Computer
  11. Select the drive that shows your jump drive( this will show either the name brand of your jump drive or removable disk)
  12. Then double click on the EMB folder, then double click on the EMBF folder, this will open the file
  13. Go back to where your designs are saved. Left click & drag your design into the EMBF folder ( It will copy the file to the EMBF folder)
  14. Remove the jump drive from your computer & insert into the Janome MB-4(USB port)
  15. Touch the file folder on the left
  16. Select the jump drive icon
  17. Select the file folder
  18. Then select the EMBF folder
  19. Select your design & select OK